

## Gabriel E. Senor, P.C.

Engineers Planners Surveyors 90 N Central Park Avenue Hartsdale, NY 10530 *Tel*: (914) 422-0070 *Fax*: (914) 422-3009 *E-Mail*: Eliot@gesenor.com

## **MEMORANDUM**

TO: FROM: SUBJECT: DATE: Town of North Castle Eliot Senor P.E. L.S. Sir John's Plaza April 26, 2021

1. As indicted by the applicant, the plans have been revised to eliminate proposed parking at the rear of the site, to avoid additional cut into the existing rock slope. The revision required relocation of the trash compactor. The plans include a vehicle turning analysis that appears to provide adequate circulation. No other modifications to the previously approved parking lot layout appear to be proposed.

## Plans are as stated.

2. It appears that the applicant is proposing modifications and or elimination of a previously approved retaining wall systems along the north and west property boundary. The plans appear to have been updated with existing topography in the areas of the rock cut and excavation at the perimeter of the parking lot. The plans also illustrate a proposed retaining wall along the northern lot line; however, a Geotechnical Report has been provided indicating that portions of the wall are not required. The plan should be updated to clarify the limits of all proposed retaining walls and limits of proposed grading and backfill above the walls on the adjoining residential properties.

## A wall will be provided along the rear of the retail property and the residential property for a continuous and aesthetic appearance. The western boundary in the far end of the parking will be rock cut similar to the existing conditions that are south of the current proposed disturbance.

3. The owner retained the services of Geotechnical Engineering Services, P.C. to evaluate the condition of the exposed rock and soil at the perimeter of the parking lot. The Report indicates that retaining walls would not be required at two sections: (1) approximately 60 feet along the north side and, (2) the entire length of the west side of the lot. The Report also notes that a site visit was

conducted on January 7, 2021, at which time it was recommended that additional cleaning and removal of loose rock and soil be performed, so that a subsequent inspection and evaluation could be done. The applicant should confirm whether this second visit took place and update the Board on their findings. Any amendment to the report should also be provided.

## Geotechnical Report to be revised.

4. The Geotechnical Report recommends two (2) options to consider for slope stability along the north property line; the first is to continue with segmental retaining walls, as originally proposed, along the entire north property line and second, provide retaining walls only at certain sections where rock and/or soil was of poor quality. In the case of the second option, this office has reservations regarding elimination of sections of walls. Based on a site visit, the exposed rock appears to be severely weathered and decomposed and likely to continue to erode over time. Given the proximity of the rock slope to the proposed parking lot and the existing residences above, we would recommend the applicant pursue Option No. 1 and provide retaining walls along the entire north property line. This will also maintain a usable rear yard for the residences above.

# Wall to be placed along residential properties. A level area will be created for plantings and a vinyl fence.

5. The Geotechnical Report indicates that the rock along the western border of the parking lot appears to be of good quality and that no rock stabilization would be required. The Report, however, also states that a return inspection should be performed after additional cleaning and chipping of loose rock and soil was completed. The Report also recommends that steel netting or fencing along this section of the rockface be considered to retain any materials that may slide over time. Based on a site visit, the rock face in this section of the parking lot appears to be approximately 30 feet high with areas of loose rock and soil. Existing trees are also immediately adjacent to the top of the cut rock face. This office is concerned with the potential for loose debris and/or rock to fall into the parking lot, as well as the potential damage that could occur with fallen trees, on the slope, immediately above the rock cut. The applicant will need to provide additional detail regarding how this cut face will provide a safe and stable slope which may include, netting, additional tree removal, additional cleaning of the rock face, a short wall and fence at the toe of the slope, or combination thereof. We would recommend the Planning Board visit the site to get a better understanding of the current conditions and proposed retaining wall layout.

# A protective 5' high fence to be provided along western line of exposed rock cut. See plan and detail (D-1)

6. The applicant has provided a revised Landscaping Plan for the Planning Board's consideration, which appears to be similar to what was previously approved.

#### Plans are as stated

7. This office witnessed deep and soil percolation testing to demonstrate that suitable soils are present for the proposed infiltration system. The plan and revised stormwater calculations, however, require coordination. The plan illustrates a total of 25 infiltration units are required to mitigate increased stormwater runoff from the parking lot expansion. However, the plan and the

hydrologic analysis indicate a total of 20 units. The plan and hydrologic calculations should be updated and coordinated as needed for further review. In addition, the pre- and post-developed drainage summaries and hydrographs provided on the plan should be reviewed and coordinated. It appears that the post-developed hydrograph for the 100-year storm event was inadvertently duplicated or incorrectly included.

## Stormwater Plan has been revised to reflect 20 cultecs.

8 As shown on the Stormwater and Erosion Control Plan, it appears that the previous limits of disturbance will be expanded slightly for additional grading in the rear of the parking lot. We would assume that the majority of this parking lot will be resurfaced. The limit of disturbance illustrated on the plans should be updated accordingly.

## Disturbance area has been revised. Actual impervious surface has decreased. (See D-2)

9. The plan should indicate where the Safety Post Detail is to be applied.

## Safety posts by compactor shown

10. Foundation requirements for the proposed fence should be incorporated into the retaining wall detail.

## Fence details added. (See D-1)

11. The plans shall include a note indicating the source of the survey and topographic data, including the referenced datum, utilized for the development of the plan.

## Survey work performed by this office Jan. 15, 2021 . (datum NAVD 88)

conducted on January 7, 2021, at which time it was recommended that additional cleaning and removal of loose rock and soil be performed, so that a subsequent inspection and evaluation could be done. The applicant should confirm whether this second visit took place and update the Board on their findings. Any amendment to the report should also be provided.

## Geotechnical Report to be revised.

4. The Geotechnical Report recommends two (2) options to consider for slope stability along the north property line; the first is to continue with segmental retaining walls, as originally proposed, along the entire north property line and second, provide retaining walls only at certain sections where rock and/or soil was of poor quality. In the case of the second option, this office has reservations regarding elimination of sections of walls. Based on a site visit, the exposed rock appears to be severely weathered and decomposed and likely to continue to erode over time. Given the proximity of the rock slope to the proposed parking lot and the existing residences above, we would recommend the applicant pursue Option No. 1 and provide retaining walls along the entire north property line. This will also maintain a usable rear yard for the residences above.

# Wall to be placed along residential properties. A level area will be created for plantings and a vinyl fence.

5. The Geotechnical Report indicates that the rock along the western border of the parking lot appears to be of good quality and that no rock stabilization would be required. The Report, however, also states that a return inspection should be performed after additional cleaning and chipping of loose rock and soil was completed. The Report also recommends that steel netting or fencing along this section of the rockface be considered to retain any materials that may slide over time. Based on a site visit, the rock face in this section of the parking lot appears to be approximately 30 feet high with areas of loose rock and soil. Existing trees are also immediately adjacent to the top of the cut rock face. This office is concerned with the potential for loose debris and/or rock to fall into the parking lot, as well as the potential damage that could occur with fallen trees, on the slope, immediately above the rock cut. The applicant will need to provide additional detail regarding how this cut face will provide a safe and stable slope which may include, netting, additional tree removal, additional cleaning of the rock face, a short wall and fence at the toe of the slope, or combination thereof. We would recommend the Planning Board visit the site to get a better understanding of the current conditions and proposed retaining wall layout.

# A protective 5' high fence to be provided along western line of exposed rock cut. See plan and detail (D-1)

6. The applicant has provided a revised Landscaping Plan for the Planning Board's consideration, which appears to be similar to what was previously approved.

#### Plans are as stated

7. This office witnessed deep and soil percolation testing to demonstrate that suitable soils are present for the proposed infiltration system. The plan and revised stormwater calculations, however, require coordination. The plan illustrates a total of 25 infiltration units are required to mitigate increased stormwater runoff from the parking lot expansion. However, the plan and the

hydrologic analysis indicate a total of 20 units. The plan and hydrologic calculations should be updated and coordinated as needed for further review. In addition, the pre- and post-developed drainage summaries and hydrographs provided on the plan should be reviewed and coordinated. It appears that the post-developed hydrograph for the 100-year storm event was inadvertently duplicated or incorrectly included.

## Stormwater Plan has been revised to reflect 20 cultecs.

8 As shown on the Stormwater and Erosion Control Plan, it appears that the previous limits of disturbance will be expanded slightly for additional grading in the rear of the parking lot. We would assume that the majority of this parking lot will be resurfaced. The limit of disturbance illustrated on the plans should be updated accordingly.

## Disturbance area has been revised. Actual impervious surface has decreased. (See D-2)

9. The plan should indicate where the Safety Post Detail is to be applied.


## Safety posts by compactor shown

10. Foundation requirements for the proposed fence should be incorporated into the retaining wall detail.

## Fence details added. (See D-1)

11. The plans shall include a note indicating the source of the survey and topographic data, including the referenced datum, utilized for the development of the plan.

## Survey work performed by this office Jan. 15, 2021 . (datum NAVD 88)




ADWG Drawings\RO#\RO20953-1.DWG, 4/26/2021 11:03:24 AM, steve, \server\Oce PlotWave 340 - WPD2

LOT AREA 68,357 SF 20.34 10.00 S09° 36' 20"W COMPACTOR PICKUP TO BE BETWEEN 3 AM - 8AM loading ------95 DRIVEW 69 77 96 \_\_\_\_\_ 68 93 78 97 \_\_\_\_\_ 67 92 79 98) <sup>TW</sup> 308 BW 303 -----66 TW 308 BW 303 91 99 80 RESERVED PARKING ACCESSIBLE SPACE SIGN 25.0' -----81 90 100 N/F EMMALON CORR ac 82 89 197 S Of a PROP LIGHT S31° 05' 76°W -----83 88 TW 305/ BW 299 102 S31. 05' 26"W 75.87 ----6.63 84) \_\_\_\_\_ 87) 103 62 RESERVED PARKING ACCESSIBLE SPACE SIGN 122.12-4-57 N/F STIPO 85 86 104 ₽☆ \_\_\_\_ 105 113  $\bigtriangledown$ -----Zone R2-F Zone CB  $\langle \neg \rangle$  $17 \omega$ <u>l</u>  $\Box$ 114 ω loading loading PROP LIG PROP LIGHT 115 Approx 300 s.f. Z PROP LIGHT (16 124 Q (17) EXIST PLS 485 PROP LIG Q 122.12-4-23 N/F STIPO 118 S (125) -11 3.3 Sir John's 3,088 sf (119) 17.75 ひら - Restaurant 120 <sup>1</sup> 3,594 sf PARKING ACCESSIBLE SPACE SIGN SLOPE PAVEMENT TO BE FLUSH WITH WALK 90 Seats Restaurant 10 Seats Bar **A** (26) 18' TYP (21) ACCESSIBLE SPACE PER DRIGINAL APPROVED SITE PLAN RESERVED PARKING ACCESSIBLE SPACE SIGN ACCESSIBLE SPACE TYPICAL 127 1 6 (22) ACCESS AISLE TYPICAL ND PARKING ACCESSIBLE AISLE SIGN (Mounted on Bldg) TTTP 128 6 133 132 131 133 129 Bidg) RESERVED PARKING ACCESSIBLE SPACE SIGN NO LEFT α HNOLEFT <u></u> EXIST 8" WATER MAIN \_\_\_\_\_ North Broadway EXIST CB (FULLED V/ DEBRIS) EXIST 8" SEWER MAIN NO LEFT TURN LOCATION OF NO LEFT TURN SIGNAGE AS SHOWN ON PLAN OF KENSICO ROAD CLOSURE TRAFFIC IMPROVEMENT MEASURES DATED JULY 2016 122.12-4-72 122.12-4-71 N/F FAVALE TRUST AND LAST REVISED MAY 18, 2018. 122.12-4-70 N/F PS HOLDING FAMILY LTD N/F RINALDI LEFT TURNS SHALL BR PROHIBITED FROM ENTERING TI AND FROM EXITING THE PROPERTY AT UNSIGNALIZED I FRONTING NIRTH BROADWAY.

| алдан стала практиски по в полити виски сили поли и поли и поли и поли поли поли | JOB NUMBER: R020953   |
|--|---|
|  | TENANTSEATS/AREAPARKING REQUIRE.SPACESSir John PlazaBAGEL SHOP8/8351/2005BEAUTY SHOP8351/1009BAKERY8/8351/2005PERSONAL SERVICE VACANT7,5151/20038SIR JOHN'S RESTURANT100/36001/7548                                       |
|  | BROADWAY PLAZA<br>N. BROADWAY DELI 825 1/75 OR 1/3 SEATS 11<br>PERSONAL SERVICE 2263 1/200 12<br>TOTAL PARKING REQUIRED 128<br>SPACES PROVIDED 127<br>COMMERCIAL SPACES 6   |
|  | TOTAL SPACES 133<br>includes 7 handicap spaces  |
|  |   |
|  |   |
|  |   |
|  | ALL SPECIFICATIONS, MATERIALS AND METHODS OF CONSTRUCTION<br>TO BE IN ACCORDANCE WITH THE TOWN CONSTRUCTION STANDARDS<br>ORDINANCE AND WITH THE REQUIREMENTS OF THE PLANNING BOARD<br>RESOLUTION OF APPROVAL DATED , 2020 |
|  | OWNER DATE  |
|  | JOSEPH M. CERMELE, P.E. DATE<br>KELLARD SESSIONS CONSULTING<br>CONSULTING TOWN ENGINEER   |
|  |   |
|  | 7APRIL 26, 2021REV SITE PLANSGA6MARCH 12, 2021REV SITE PLANSGA5APRIL 29, 2020RES. COMMENTSSGA4FEB 14, 2020PER RESOLUTIONSGA3JAN 24, 2020SGA   |
|  | 2NOV 7, 2019SGA1APRIL 29, 2019SGANODATEDESCREVISIONS  |
|  | COMMERCIAL PARKING<br>SIR JOHN'S PLAZA<br>NORTH BROADWAY<br>LOCATED IN THE<br>TOWN OF NORTH CASTLE  |
|  | WESTCHESTER COUNTY, NEW YORK.   |
|  | <b>GABRIEL E. SENOR, P.C.</b><br>CONSULTING ENGINEER &LAND SURVEYORS<br>90 NORTH CENTRAL AVE., HARTSDALE, NEW YORK, 10530<br>(914) 422-0070 FAX 422-3009  |
|  | SCALE: 1" = 20'   DATE: APRIL 23, 2019   DRAWN BY:   CHECKED BY:   MCN.   P-1   |

| THE PROPERTY<br>D DRIVEWAYS |  |
|-----------------------------|--|
|                             |  |

SHEET 1OF 6



PERCOLATION TESTING IN THE VICINITY OF THE PROPOSED MITIGATION SYSTEM TO BE WITNESSED BY THE TOWN ENGINEER. THE TEST LOCATIONS AND RESULTS SHALL BE SHOWN ON THE PLAN, ANY MODIFICATIONS TO THE STORM SYSTEM THAT MAY BECOME NECESSARY SHALL BE SUBMITTED FOR

BY GABRIEL E SENOR PC JAN 15, 2021. DATUM SHOWN IS NAVD 88

## JOB NUMBER: R020953

| ZONING COMPLIANCE CB LOT 54 |               |                |  |  |  |  |
|-----------------------------|---------------|----------------|--|--|--|--|
|                             | REQUIRED      | PROPOSED       |  |  |  |  |
| Lot Area (Sq.ft.)           | 5,000 Sq. Ft. | 68357 Sq. Ft.  |  |  |  |  |
| Frontage                    | 50'           | 186.68         |  |  |  |  |
| Depth                       | 100'          | 400' +/-       |  |  |  |  |
| Front                       | 10'           | 18.3           |  |  |  |  |
| Side                        | 0<br>6**      | 3.3'<br>14.4** |  |  |  |  |
| Rear                        | 30            | 43.3           |  |  |  |  |
| Bldg coverage<br>Coverage   | 35%           | 10%            |  |  |  |  |
| Bldg Height                 | 2             | 1              |  |  |  |  |
| FAR                         | 0.4           | .10            |  |  |  |  |

\*\* Abuts Residential District R-2F OWNERS JOHN A. MAGNOTTA REALTY, INC. 913 NORTH BROADWAY WHITE PLAINS , NY 10603

EMMALON CORP. 1 HILLAIR CT WHITE PLAINS, NY 10605

TAX ASSESSMENT MAP DESIGNATION :

122.12-4-56 122.12-4-54

122.12-4-53

ALL SPECIFICATIONS, MATERIALS AND METHODS OF CONSTRUCTION TO BE IN ACCORDANCE WITH THE TOWN CONSTRUCTION STANDARDS ORDINANCE AND WITH THE REQUIREMENTS OF THE PLANNING BOARD RESOLUTION OF APPROVAL DATED , 2020

PLANNING BOARD CHAIRMAN OWNER

DATE

DATE

DATE


KELLARD SESSIONS CONSULTING CONSULTING TOWN ENGINEER

JOSEPH M. CERMELE, P.E.


REVISION REV SITE PLAN SGA 5 APRIL 26, 2021 4 MARCH 12, 2021 REV SITE PLAN SGA 3 RES. COMMENT SGA APRIL, 29 2020 2 SGA JAN 24, 2020 DEC 9, 2019 SGA NO DATE DESC BY REVISIONS

SIR JOHN'S PLAZA 913 NORTH BROADWAY LOCATED IN THE TOWN OF NORTH CASTLE

WESTCHESTER COUNTY, NEW YORK.



SHEET 2 OF 6



JOB NUMBER: R020953

| ya na para ya mwana na kata mwa mwana mafika 2020 mwa mwa mwa mwana kata mwa kata kata kata kata kata kata kat |                   |                |  |  |  |  |  |
|--|-------------------|----------------|--|--|--|--|--|
| ZON  | ING COMPLIANCE CE | 3 LOT 54       |  |  |  |  |  |
| REQUIRED<br>ALLOWABLE PROPOSED   |                   |                |  |  |  |  |  |
| Lot Area (Sq.ft.)  | 5,000 Sq. Ft.     | 68357 Sq. Ft.  |  |  |  |  |  |
| Frontage   | 50'               | 186.68         |  |  |  |  |  |
| Depth  | 100'              | 400' +/-       |  |  |  |  |  |
| Front  | 10'               | 18.3'          |  |  |  |  |  |
| Side   | 0<br>6**          | 3.3'<br>14.4** |  |  |  |  |  |
| Rear   | 30                | 43.3           |  |  |  |  |  |
| Bldg coverage<br>Coverage  | 35%               | 10%            |  |  |  |  |  |
| Bldg Height  | 2                 | 1              |  |  |  |  |  |
| FAR  | 0.4               | .10            |  |  |  |  |  |

\*\* Abuts Residential District R-2F OWNERS JOHN A. MAGNOTTA REALTY, INC. 913 NORTH BROADWAY WHITE PLAINS , NY 10603

EMMALON CORP. 1 HILLAIR CT WHITE PLAINS, NY 10605

TAX ASSESSMENT MAP DESIGNATION :

122.12-4-56 122.12-4-54

122.12-4-53

ALL SPECIFICATIONS, MATERIALS AND METHODS OF CONSTRUCTION TO BE IN ACCORDANCE WITH THE TOWN CONSTRUCTION STANDARDS ORDINANCE AND WITH THE REQUIREMENTS OF THE PLANNING BOARD RESOLUTION OF APPROVAL DATED , 2020

PLANNING BOARD CHAIRMAN

OWNER

DATE

DATE


DATE

JOSEPH M. CERMELE, P.E. KELLARD SESSIONS CONSULTING CONSULTING TOWN ENGINEER


|           |                | ·             |     |  |  |  |
|-----------|----------------|---------------|-----|--|--|--|
| REVISION  | · ·            |               |     |  |  |  |
|           |                |               |     |  |  |  |
|           |                |               |     |  |  |  |
|           |                |               |     |  |  |  |
|           |                |               |     |  |  |  |
| 7         | APRIL 26, 2021 | REV SITE PLAN | SGA |  |  |  |
| 6         | MARCH 12, 2021 | REV SITE PLAN | SGA |  |  |  |
| 5         | FEB 24, 2021   | DRAINAGE      | SGA |  |  |  |
| 4         | APRIL, 29 2020 | RES. COMMENT  | SGA |  |  |  |
| 3         | MARCH 17, 2020 | DPW           | SGA |  |  |  |
| 2         | JAN 24, 2020   |               | SGA |  |  |  |
| 1         | DEC 9, 2019    |               | SGA |  |  |  |
| NO        | DATE           | DESC          | BY  |  |  |  |
| REVISIONS |                |               |     |  |  |  |


SIR JOHN'S PLAZA 913 NORTH BROADWAY LOCATED IN THE TOWN OF NORTH CASTLE

WESTCHESTER COUNTY, NEW YORK.



SHEET 3 OF 6






| PRESOAK DAT<br>PERCOLATION<br>NO ROCK OR V     | TEST DATE:                     | 1/15/21 BOT ELEV F            | 'ERC 290.24         | -/-                                 |
|--|--------------------------------|-------------------------------|---------------------|-------------------------------------|
| PERC HOLE 1                                    |                                |                               |                     |                                     |
| START<br>12:37<br>12:46<br>1:01                | END<br>12:46<br>1:01<br>1:16   | TIME ELAPED<br>9<br>15<br>15  | DROP<br>4<br>4<br>4 | RATE MIN/IN<br>2.25<br>3.75<br>3.75 |
| PERC HOLE 2                                    |                                |                               |                     |                                     |
| START<br>12:36<br>12:51<br>1:06<br>PERC HOLE 3 | END<br>15:51<br>1:06<br>1:21   | TIME ELAPED<br>15<br>15<br>15 | DROP<br>5<br>5<br>5 | RATE MIN/IN<br>3<br>3<br>3          |
| START<br>12:40<br>12:45<br>12:50<br>ERC HOLE 4 | END<br>12:45<br>12:50<br>12:55 | TIME ELAPED<br>5<br>5<br>5    | DROP<br>4<br>4<br>4 | RATE MIN/IN<br>.8<br>.8<br>.8       |
| START<br>12:36<br>12:45<br>12:50               | END<br>12:39<br>12:48<br>12:53 | TIME ELAPED<br>3<br>3<br>3    | DROP<br>4<br>4<br>4 | RATE<br>1.33<br>1.33<br>1.33        |

| Summary | for | Reach | P1: | 10" | PIPI |
|---------|-----|-------|-----|-----|------|

>\DWG Drawings\RO#\RO20953-1.DWG, 4/25/2021 11:10:38 AM, steve,


server\Oce PiotWave 340 - WPD2


| Summary for Subcatchment Pre: Pre-Dev |  |        |           |                   |   |        |  |  |  |
|---------------------------------------|--|--------|-----------|-------------------|---|--------|--|--|--|
| Runoff                                | =  | 0.74 c | fs@ 12.   | 18 hrs Vo         | lume= 0.059 af Depth=3.38"  |        |  |  |  |
|                                       | Runoff by SCS TR-20 method, UH=SCS, Weighted-CN, Time Span= 0.00-48.00 hrs, dt= 0.05 hrs<br>NRCC 24-hr C 25yr Rainfall=6.47" |        |           |                   |   |        |  |  |  |
| . A                                   | rea (sf)   | CN D   | escriptio | n                 |   |        |  |  |  |
|                                       | 9,047  | 72 V   | /oods/gra | ass comb          | ., Good, HSG C  |        |  |  |  |
|                                       | 9,047  | 1      | 00.00%    | Pervious          | Vea   |        |  |  |  |
| Tc<br>(min)                           | Length<br>(feet)   |        |           | Capacity<br>(cfs) | Description   |        |  |  |  |
| 4.1                                   | 47   |        | 0.19      | ()                | Sheet Flow,   |        |  |  |  |
| 5.6                                   | 31   | 0.0500 | 0.09      | ·                 | Woods: Light underbrush n= 0.400<br>Sheet Flow,<br>Woods: Light underbrush n= 0.400 |        |  |  |  |
| 0.3                                   | 57   | 0.0500 | 3.60      |                   | Shallow Concentrated Flow,<br>Unpaved Kv= 16.1 fps                                  |        |  |  |  |
| 0.0                                   | 8  | 0.6700 | 13.18     |                   | Shallow Concentrated Flow,<br>Unpaved Kv= 16.1 fps                                  |        |  |  |  |
| 10.0                                  | 143  | Total  |           |                   |   |        |  |  |  |
|                                       | · · · · · · · · · · · · · · · · · · ·  |        |           |                   |   |        |  |  |  |
|                                       | Hydrograph   |        |           |                   |   |        |  |  |  |
|                                       | ก ด เป   | 1      | 0.74 cf   | s                 |   | Runoff |  |  |  |




|  | 1      |         | i may raquira | onnanon ac        |                     |         |  |
|--|--------|---------|---------------|-------------------|---------------------|---------|--|
|  | Runoff | =       | 1.53 cfs@     | 12.06 hrş Volume= | 0.108 af Depth=6.23 | 3″      |  |
| Nunoff by SCS TR-20 method, UH=SCS, Weighted-CN, Time Span= 0.00-48.00 hrs, dt= 0.<br>NRCC 24-hr C 25yr Rainfall=6.47" |        |         |               |                   |                     |         |  |
|  |        | ea (sf) | CN Descri     | ption             |                     | · · · · |  |

|             | 9,047            | 1                | 00.00% | Imperviou | s Area          |             |           |
|-------------|------------------|------------------|--------|-----------|-----------------|-------------|-----------|
| Tc<br>(min) | Length<br>(feet) | Slope<br>(ft/ft) |        |           | Description     |             |           |
| 0.7         | 100              | 0.0670           | 2.33   |           | Sheet Flow,     |             |           |
|             |                  |                  |        |           | Smooth surfaces | n= 0.011    | P2= 3.50" |
| 0.1         | 45               | 0.0670           | 5.25   |           | Shallow Concen  | trated Flov | ν,        |
|             |                  |                  |        |           | Paved Kv= 20.3  | íps         |           |
| 00          | 145              | Total            |        | **        |                 |             |           |









# - Retaining Wall NOT Required

- 40 ft wide, 6 to 9 ft high - Poor Rock Quality and Soil - Retaining Wall recommended to full height of excavation

## JOB NUMBER: R020953 TENANT SEATS/AREA PARKING REQUIR Sir John Plaza

BAGEL SHOP 1/200 BEAUTY SHOP 835 1/100 1/200 BAKERY 8/835 PERSONAL SERVICE VACAN 7,515 1/200 100/3600 1/75 SIR JOHN'S RESTURAN BROADWAY PLAZA 1650 1/75 OR 1/9 SEATS

N. BROADWAY DELI PERSONAL SERVICE

1438 1/200

TOTAL PARKING REQUIRE SPACES PROVIDED COMMERCIAL SPACES TOTAL SPACES Includes 7 handicap spaces

SPACES

Christopher Carthy

PLANNING BOARD CHAIRMAN

Jutonto

07/01/20

DATE

06/<u>29/20</u>

AUSEPH M. CERMELE, P.E. RELLARD SESSIONS CONSULTING CONSULTING TOWN ENGINEER

|          | n sega an saga s |                | la di bilan di sur di sur<br>Sur di sur di |
|----------|------------------|----------------|--|
|          |                  |                |  |
|          |                  |                | an che management a che de la che de la construir de la della de la construir de la construir de la construir d  |
|          |                  |                |  |
|          |                  |                |  |
|          |                  |                |  |
|          |                  |                |  |
|          |                  |                | gerrer i netar negaritzi kuantura (sanda i sanda i sand  |
| 5        | APRIL 29, 2020   | RES. COMMENTS  | SGA  |
| 4        | FEB 14, 2020     | PER RESOLUTION | SGA  |
| 8        | JAN 24, 2020     |                | SGA  |
| 2        | NOV 7, 2019      |                | SGA  |
|          | APRIL 29, 2019   |                | SGA  |
| NO       | DATE             | DESC           | BY   |
| REVISION |                  |                |  |

COMMERCIAL PARKING SIR JOHN'S PLAZA NORTH BROADWAY TOWN OF NORTH CASTLE

WESTCHESTER COUNTY, NEW YORK.

CONSULTING ENGINEER .LAND SURVEYORS 90 NORTH CENTRAL AVE., HARTSDALE, NEW YORK, 10530 (914) 422-0070 FAX 422-3009 SCALE: 1" = 20' DATE: APRIL 23, 2019 DRAWN BY: CHECKED BY: MON. 665. Geotechnica

and and SHEETGOF 6