

Section I- PROJECT

TOWN OF NORTH CASTLE

WESTCHESTER COUNTY 17 Bedford Road Armonk, New York 10504-1898

RESIDENTIAL PROJECT REVIEW COMMITTEE Adam R. Kaufman AICP, Chair

ADDRESS: 45 BYRAM RIDGE ROAD

Section III- DESCRIPTION OF WORK:

Telephone: (914) 273-3000 x 43 Fax: (914) 273-3554

www.nortcastleny.com

RESIDENTIAL PROJECT REVIEW COMMITTEE (RPRC) APPLICATION

NEW HOME	
ection III- CONTACT INFORMATION:	
PPLICANT: JOSEPH DANIEL	_
DDRESS: 9 Cole DR	
HONE: 403-8880 MOBILE: EMAIL TOSEPH DANIEL OMSN. COM	_
ROPERTY OWNER: JOSEPH DANIEZ	
DDRESS:	
HONE:MOBILE:EMAIL:	_
ROFESSIONAL: ETIST SENOR	
DDRESS: 90 N. CENTRAL AVE HARTEDALE NY	_
HONE: 422-0070 MOBILE:	_
MAIL: ENGINEERS GESENOR, COM	-
ection IV- PROPERTY INFORMATION:	
Tax ID (lot designation) 101,03-3-24	_



RESIDENTIAL PROJECT REVIEW COMMITTEE ENGINEERING REVIEW		
Date	August 14, 2020	
Project Name	Joseph Daniel	
Street Location	45 Byram Ridge Road	
Section, Block & Lot	101.03/3/24	

Engineering Comments:

- The location of the property line should be clarified. There appears to be two similar lines offset with dimension pulled to each.
- The site plan shall illustrate the entire property limits.
- Provide an Existing Conditions Plan illustrating all features and those to be removed, including but not limited to, the residence, drive, walks, well, septic, overhead utilities, etc.
- Illustrate existing topography.
- The improvements within the Town right-of-way will require a Street Opening Permit from the Highway Department. All proposed improvements shall be detailed, per the Town Highway Department standards.
- The plan shall demonstrate that the minimum required Westchester County Department of Health (WCHD) setbacks to the infiltration system/domestic well/proposed improvements are met. The proposed storm connection for the slot drain is not shown on the plan. Assuming it will discharge to the infiltration system, we note that the WCHD requires a separation of 100 feet to a drilled well for infiltration systems collecting runoff from paved surfaces (drives). The plan shall be revised accordingly.
- The Slot Drain Detail does not seem appropriate for use in the drive. Please replace the structure with one suitable for H-20 loading.
- Provide a copy of the WCHD Approval for the proposed modifications/replacement of the on-site wastewater treatment system and drilled well.
- The plan shall illustrate and quantify the limits of disturbance. The plan shall note that disturbance limits shall be staked in the field prior to construction.
- The plan shall illustrate the areas of the proposed septic field and infiltration area to be cordoned off from construction traffic during construction.

CIVIL ENGINEERING | LANDSCAPE ARCHITECTURE | SITE & ENVIRONMENTAL PLANNING

Residential Project Review Committee Daniel – 45 Byram Ridge Road August 14, 2020 Page 2 of 2


- As shown, it appears that at least two (2) additional trees will require removal in the vicinity of the infiltration system and associated grading, as well as 3-4 trees for the proposed septic field and grading. This should be reviewed and revised, as needed. The plan shall also clearly illustrate all existing trees to be protected.
- Provide a Landscape Plan.
- The proposed finished floor elevation is shown to only be six (6) inches above adjacent surrounding grade. Please verify and revise as needed.
- Provide stormwater mitigation and design calculations for the runoff generated by the net increase in impervious surface for the 100-year, 24-hour design storm event. Rainfall data shall be taken from the NRCS Extreme Precipitation Data.
- The plan should locate the proposed footing drain discharge, as well as the area drain for the exterior basement window wells.
- All proposed drain pipes, including the roof drain piping, should have a minimum of one (1) foot of soil cover.
- Provide construction details for the proposed pipe trenching, pavement, curbing and roof leaders.
- The Trench Drain Detail indicates a four (4) inch total height. However, six (6) inch diameter piping is proposed. The trench drain should be revised to accommodate the six (6) inch pipe and adequate cover.
- An emergency overflow control must be provided for the infiltration system.

Plan Reviewed, prepared by Gabriel E. Senor, P.C., dated July 30, 2020:

Stormwater Pollution Prevention Plan and Erosion Control Plan (Sheet 1 of 1)

Signed:

Joseph M. Cermele P.E., CFM, Consulting Town Engineer



Gabriel E. Senor, P.C.

Engineers Planners Surveyors

90 N Central Park Avenue Hartsdale, NY 10530

Fax: (914) 422-3009 E-Mail: info@gesenor.com

(914) 422-0070

01/20/2021

To: Town of North Castle Residential Project Review Committee & Planning Dept

Re: 45 Byram Ridge Rd – Section 101.03 Block 3 Lot 24

Tel:

Dear Members of the RPRC and Planning Board,

Below are responses to the questions/comments received 08/14/2020:

Residential Project Review Committee Comments

- The location of the property line should be clarified. There appears to be two similar lines offset with dimension pulled to each.
 - Property line location corrected.
- The site plan shall illustrate the entire property limits.
 - Site plan now illustrates the entire property limits.
- Provide an Existing Conditions Plan illustrating all features and those to be removed, including but not limited to, the residence, drive, walks, well, septic, overhead utilities, etc.
 - See "Topographic Map and Existing Conditions/Removals Plan"
- Illustrate existing topography.
 - See "Topographic Map and Existing Conditions/Removals Plan"
- The improvements within the Town right-of-way will require a Street Opening Permit from the Highway Department. All proposed improvements shall be detailed, per the Town Highway Department standards.
 - Note added to existing curb cut.
- The plan shall demonstrate that the minimum required Westchester County Department of Health (WCHD) setbacks to the infiltration system/domestic well/proposed improvements are met. The proposed storm connection for the slot drain is not shown on the plan. Assuming it will discharge to the infiltration system, we note that the WCHD requires a separation of 100 feet to a drilled well for infiltration systems collecting runoff from paved surfaces (drives). The plan shall be revised accordingly.
 - All dimensions corresponding to WCHD requirements have been labeled.
- The Slot Drain Detail does not seem appropriate for use in the drive. Please replace the structure with one suitable for H-20 loading.
 - See new detail
- Provide a copy of the WCHD Approval for the proposed modifications/replacement of the on-site wastewater treatment system and drilled well.
 - Will provide on receipt
- The plan shall illustrate and quantify the limits of disturbance. The plan shall note that disturbance limits shall be staked in the field prior to construction.



GABRIEL E SENOR P.C.

Page 1 of 3 45 Byram Ridge Rd

Response to RPRC & Planning Department Review Comments

- Noted and limits identified.
- The plan shall illustrate the areas of the proposed septic field and infiltration area to be cordoned off from construction traffic during construction.
 - Fence shown.
- As shown, it appears that at least two (2) additional trees will require removal in the vicinity of the infiltration system and associated grading, as well as 3-4 trees for the proposed septic field and grading. This should be reviewed and revised, as needed. The plan shall also clearly illustrate all existing trees to be protected.
 - Additional trees shown to be removed and tree protection shown
- Provide a Landscape Plan.
 - Landscape Plan Provided
- The proposed finished floor elevation is shown to only be six (6) inches above adjacent surrounding grade. Please verify and revise as needed.
 - First floor elevation and grading revised
- Provide stormwater mitigation and design calculations for the runoff generated by the net increase in impervious surface for the 100-year, 24-hour design storm event. Rainfall data shall be taken from the NRCS Extreme Precipitation Data.
 - Plan has been revised for a 100 year storm.
- The plan should locate the proposed footing drain discharge, as well as the area drain for the exterior basement window wells.
 - Additional cultec provided for the footing drain discharge. Window well drain to be tied into footing drains.
- All proposed drain pipes, including the roof drain piping, should have a minimum of one (1) foot of soil cover.
 - All piping now has 1 ft of cover.
- Provide construction details for the proposed pipe trenching, pavement, curbing and roof leaders.
 - Curbing and trench details are on the plan sheet
- The Trench Drain Detail indicates a four (4) inch total height. However, six (6) inch diameter piping is proposed. The trench drain should be revised to accommodate the six (6) inch pipe and adequate cover.
 - Detail has been revised
- An emergency overflow control must be provided for the infiltration system.
 - Emergency overflow has been added (Pop Up Emitter)

Planning Dept Comments

The property is a corner lot. Pursuant to Section 355-15.I of the Town Code, on any corner lot, except in an R-5 District, there shall be provided a side yard on the side street equal in depth to the required front yard on said lot; therefore, the Byram Ridge Road side yard is required to have a 50 foot setback. The site plan will need to be revised.

- Setback has been revised

The site plan should be revised to include a zoning conformance table.

- Zoning table has been added.

8 trees are proposed to be removed. It is recommended that the Applicant provide a landscaping plan for review.



GABRIEL E SENOR P.C.

Page 2 of 3 45 Byram Ridge Rd

Response to RPRC & Planning Department Review Comments

- Landscape plan provided.

The maximum exterior wall height calculation on the left side is not correct. Max Exterior Wall Height should be measured from the bottom of the proposed well to the midpoint of the roof.

- Architect revised

It is not clear whether the existing curbcut is going to be preserved. The site plan should be revised to depict that adequate sight distance is provided at the driveway. If a new curbcut/driveway is proposed, the Applicant will need to obtain a curbcut permit from the Highway Department.

- Existing curb cut will be restored and contractor will obtain permit from highway dept.

The gross land coverage calculations worksheet has a GLC of 5,883 square feet while the backup data depicts a GLC of 5,800. The discrepancy should be addressed.


- The correct GLC calculations are submitted with this response

The gross floor area calculations worksheet has a GFA of 6,369 square feet while the backup data depicts a GFA of 6,341 square feet. The discrepancy should be addressed.

- The correct GFA calculations are submitted with this response

Given that the site plan has to be revised to relocate the house and a landscaping plan has not been submitted it is recommended that the Applicant return to the RPRC for an additional review.

If you need any further clarification, please contact me.
Sincerely,
Eliot Senor P.E.



Westchester County, New York

ChB—Charlton fine sandy loam, 3 to 8 percent slopes

Map Unit Setting

National map unit symbol: 2wh0n

Elevation: 0 to 1,440 feet

Mean annual precipitation: 36 to 71 inches Mean annual air temperature: 39 to 55 degrees F

Frost-free period: 140 to 240 days

Farmland classification: All areas are prime farmland

Map Unit Composition

Charlton and similar soils: 85 percent Minor components: 15 percent

Estimates are based on observations, descriptions, and transects of

the mapunit.

Description of Charlton

Setting

Landform: Hills, ground moraines, ridges

Landform position (two-dimensional): Backslope, shoulder, summit Landform position (three-dimensional): Crest, side slope, nose

slope

Down-slope shape: Linear, convex Across-slope shape: Convex

Parent material: Coarse-loamy melt-out till derived from granite,

gneiss, and/or schist

Typical profile

Ap - 0 to 7 inches: fine sandy loam

Bw - 7 to 22 inches: gravelly fine sandy loam C - 22 to 65 inches: gravelly fine sandy loam

Properties and qualities

Slope: 3 to 8 percent

Depth to restrictive feature: More than 80 inches

Drainage class: Well drained

Runoff class: Low

Capacity of the most limiting layer to transmit water (Ksat): Moderately low to high (0.14 to 14.17 in/hr)

Depth to water table: More than 80 inches

Frequency of flooding: None Frequency of ponding: None

Maximum salinity: Nonsaline (0.0 to 1.9 mmhos/cm) Available water capacity: Moderate (about 6.9 inches)

Interpretive groups

Land capability classification (irrigated): None specified

Land capability classification (nonirrigated): 2e

Hydrologic Soil Group: B

Ecological site: F144AY034CT - Well Drained Till Uplands

Hydric soil rating: No

Minor Components

Sutton

Percent of map unit: 8 percent Landform: Ground moraines, hills

Landform position (two-dimensional): Footslope Landform position (three-dimensional): Base slope

Down-slope shape: Concave Across-slope shape: Linear Hydric soil rating: No

Paxton

Percent of map unit: 5 percent

Landform: Drumlins, hills, ground moraines

Landform position (two-dimensional): Backslope, summit, shoulder

Landform position (three-dimensional): Side slope, crest

Down-slope shape: Linear, convex Across-slope shape: Convex Hydric soil rating: No

Leicester

Percent of map unit: 1 percent

Landform: Drainageways, depressions

Down-slope shape: Linear Across-slope shape: Concave

Hydric soil rating: Yes

Chatfield

Percent of map unit: 1 percent

Landform: Hills, ridges

Landform position (two-dimensional): Backslope, shoulder, summit Landform position (three-dimensional): Crest, side slope, nose

slope

Down-slope shape: Convex

Across-slope shape: Linear, convex

Hydric soil rating: No

Data Source Information

Soil Survey Area: Westchester County, New York Survey Area Data: Version 16, Jun 11, 2020

WESTCHESTER COUNTY DEPARTMENT OF HEALTH

Bureau of Environmental Quality 118 North Bedford Road Mount Kisco, NY 10549

DESIGN DATA SHEET - SEPARATE SE	WAGE S	YSTEM	WCDH FILE #	
Owner	Address_	45 Byran	Ridge Pol,	
Property Location:(Indicate nearest cross street	n	Sec	Block	_Lot
MunicipalityWatershed		NYCEP:	Joint Review 🗆	Delegated □
SOIL PERCOLATION TEST DATA REQ	UIRED TO	O BE SUBMIT	TED WITH PPLIC	CATION
Presoak Date: 2		Run Date	2/23/21	

	Hole #		CLOCE	TIME				RCOLAT	
	Hole Number	Run No.	Start	Stop	Elapse Time Min.	Depth to From Ground Start Inches	Stop Inches	Water Level Drop In Inches	Soil Rate Min/in Drop
On trist		1	2:33	2:37	6	12"	15"	3	2
Dar test		2	2:40	2:50	10	12"	15"	3	
		3	2:50	3/01	11	12"	15"	3	
	-	4	3:01	3;12	11	12"	15"	3	i
		5		1	1				
15+ 42	-		3:03	3:08	5	12"	150	3	1
ich and		2	3:09	3:14	\$	12"	1511	3	i
		3	3:14	3420	6	12"	15"	3	_i
		4						<u> </u>	
		5	1		1	1			
		1					1	1	
		2						1	
	-	3							
		4			i			<u> </u>	
		5		į	1		1	1	

Perc test done by:__

2. Depth measurements to be made from top of hole. DO NOT REPORT INCREMENTS OF LESS THAN ONE INCH.

Tests to be repeated at same depth until approximately equal soil rates are obtained at each percolation test hole. All data to be submitted for review.



TOWN OF NORTH CASTLE

WESTCHESTER COUNTY 17 Bedford Road Armonk, New York 10504-1898


PLANNING DEPARTMENT Adam R. Kaufman, AICP Director of Planning


Telephone: (914) 273-3542 Fax: (914) 273-3554 www.northcastleny.com

GROSS LAND COVERAGE CALCULATIONS WORKSHEET

Annlicat	ion Name or Identifying Title:	45 Byram Ridge Rd	Date: 01/29/2021
		101.02 2 24	
	Designation or Proposed Lot No.:	101.03 - 3 - 24	
Gross Lo	ot Coverage		
1.	Total lot Area (Net Lot Area for Lot	s Created After 12/13/06):	48,029 SF
2.	Maximum permitted gross land cov	erage (per Section 355-26.C(1)(b)):	9,752.2 SF
3.	BONUS maximum gross land cover	(per Section 355-26.C(1)(b)):	
	Distance principal home is beyond n	ninimum front yard setback	1 SF
4.	TOTAL Maximum Permitted gros	ss land coverage = Sum of lines 2 and 3	9,753.2 SF
5.	Amount of lot area covered by princ existing +		3,205 SF
6.	Amount of lot area covered by access		0 SF
7.	Amount of lot area covered by deckexisting +		0 SF
8.	Amount of lot area covered by porc existing +		316 SF
9.	Amount of lot area covered by drive existing +	eway, parking areas and walkways: proposed =	2,134 SF
10.	Amount of lot area covered by terra existing +		299 SF
11.	Amount of lot area covered by tennie existing +	is court, pool and mechanical equip: proposed =	8 SF
12.	Amount of lot area covered by all o		0 SF
13.	Proposed gross land coverage: Tot	al of Lines 5 – 12 =	5,962 SF
the projection does not	3 is less than or equal to Line 4, you get may proceed to the Residential Processing With the Town's regulations. e and Seal of Professional Preparing	OF NEW L	e 13 is greater than Line 4 your proposa 3-2-2021

TOTAL IMPERVIOUS SURFACE = 5954 SF






See Title 19 NYCRR Part 1265 For Other Specs

2020 Residential Code Of New York State

			Cli	matic & o	Geographi	ic De	esign Cr	iteria -	Table R301	.2(1)					
Ground		Wind Desi	'an		Seis	mic	Subject	To Dama	ge From	Winter	Ice Shield	Flood	Air Fr	eezinq	Mean Annual
Snow Load	Speed (mph)	Topographic Effects	Special Wind Region	Wind-Bo Debris			Weathering	Frost Line Depth	Termite	Design Temp.	Underlayment Required	Hazards	Inde	ex	Temperature
30 lb/ft	115 - 120 mph	No	Yes	Zone	: І В		Severe	42"	Moderate Heavy	7º F	Yes	No	1500 d	or Less	52.2 F
	Elevation	Latitude	e Mini Hea		Manual Summer Cooling	\neg		orrection	Indoor Temp	r Design erature	Desig	n Tempero Cooling	ature	Heatin I	g Temperature Difference
	436	41	7		87		1			68		75			61
Cooling T	Temperature Difference	Wind Veloc Heating			Coincident Wet Bulb		Daily F	Range	Winter	Humidity	Surr	nmer Humic	lity		
	12	20.4	7.	5	7.5		М			30		55			

	Name:	Type:	Color
Siding:	Cedar Clapboard	Bevel Siding	White
Windows:	Marvin (Integrity Series)	Double Hung	Black
Trim:	Azek	Composite	White
Front Door:	n/a	Composite	Black
Garage Door:	n/a	Composite	White
Roofing:	GAF	Asphalt	Pewter
Shutters:	n/a	n/a	n/a
Gutter/Leaders:	n/a	Aluminum	White





50	uare	Footag	e
	•	2	
	•		

First Floor	2,533	Sf
Second Floor	3,331	Sf
Total	5,864	Sf

DeMasi Architects
239 LEXINGTON AVENUE, MOUNT KISCO, NEW YOR




Town Comments | 11/11/20 RPRC Date Revision

April 29, 2020

Job No 220-024 Drawing





1000 to Not 500

rchitects P.C MOUNT KISCO, NEW YORK 10549

239 LEXINGTON AVENUE, N

CISTERED ARCH CISTER

plans are the property of the Architect. Any use or buction in whole or part without the written authorization Architect is prohibited. Any person or corporation blans without proper authorization will be responsible to nsate the Architect.

plans are not valid for a building permit unless ally signed and sealed by the Architect and are for the outlin of one Structure only by the person whose name

Byram Ridge Ra

Town Comments | II/II/20


Revision Date

April 29, 2020

Job No

220-024
Drawing

2 of 8



10549

N AVENUE, MOUNT KISCO, NEW

(914) 666-3858



These plans are the property of the Architect. Any use or reproduction in whole or part without the written authorization of the Architect is prohibited. Any person or corporation using plans without proper authorization will be responsible to compensate the Architect.

These plans are not valid for a building permit unless originally signed and sealed by the Architect and are for the construction of one Structure only by the person whose name appears on the plans.

com Ridge Ro

Residence For 45 Byram

Town Comments 11/11/20


Revision Date

Date
April 29, 2020


Job No 220-024

Drawing

2 A of &



Steel Beam Detail @ Garage Scale: I" = 1'-0"



Interior Crown Detail

Scale : |" = |'-0"

Notes: All Framing Members To Be # 2 Douglas Fir- Larch Or Better Double Frame Under All Partitions Parallel To Framing If Tile Floor is To Be MUD Job Consult Architect For Additional Framing Required

Legend:


- 2 x Wood Post (Match Beam Width or As Noted Smoke Detector
 w/ Battery Back-Up
- CD Carbon Monoxide Del w/Battery Back-Up Carbon Monoxide Det
- HD Heat Detector
 w/ Battery Back-Up Recessed Light Fixture
- Surface Mounted Light Duplex Outlet
 Ground Fault Interrupter
 (GFI) At All Met Areas
- (As Required By Code) Exhaust Fan

Mood Header Schedule

<u>Span</u>	Header Size
Up To 3'-0"	(2) 2 x 8 Hdr
Up To 4'-0"	(2) 2 x 10 Hdr
Up To 6'-0"	(3) 2 x 10 Hdr
Note:	
Unless Otherwis	se Noted On Plans

Mindow Note:

- All Glazing To Be Low "E" Insulated Glass w/ Minimum R-3.I (U=0.32). All Windows Within 18" Of Floor To Have Tempered Glass (Double Hung's-Bottom Sash Only, All Others Full Unit.).
- All Glazing In Doors & Windows Enclosing Hot Tubs, Whirlpool Tubs, Saunas, Steam Rooms, Bathtubs and Showers Within 60" Of Window or Door Unit Shall Have
- All Egress Windows To Have A Minimum Clear Opening Area Of 5.7 Sf Total w/ 24" min Clear Opening Height & 20" min Clear Width. Refer To Manufactures Specifications For All Other Information.
- All Windows or Doors Marked w/ "TEMP" To Have Full Unit Tempered.



 \bigcirc 11 P

Residence

Revision

Job No

Drawing

Town Comments | 11/11/20

Date


April 29, 2020

220-024

47

chitect

First Floor Plan



 $\| \mathcal{O} \|$

5 Architect ENUE, MOUNT KISCO, NEW Y

DeMasi239 LEXINGTON AVE

Town Comments | 11/11/20


Date Revision

Job No 220-024

April 29, 2020

Drawing

OF 1



ts.com

Lects P.C. 500, NEW YORK 10549

JOI AFORITOCTO

239 LEXINGTON AV

CONTERED ARCHITECTURE OF NEW YORK

plans are the property of the Architect. Any use or action in whole or part without the written authorization Architect is prohibited. Any person or corporation ans without proper authorization will be responsible to sate the Architect.

Plans are not valid for a building permit unless by signed and sealed by the Architect and are for the cition of one Structure only by the person whose name so on the plans.


Byram Ridge Ra


Town Comments 11/11/20

Revision Date
Date
April 29, 2020


Job No 220-024


Drawing






	Name:	Type:	Color:
Siding:	Cedar Clapboard	Bevel Siding	White
Windows:	Marvin (Integrity Series)	Double Hung	Black
Trim:	Azek	Composite	White
Front Door:	n/a	Composite	Black
Sarage Door:	n/a	Composite	White
Roofing:	GAF	Asphalt	Penter
Shutters:	n/a	n/a	n/a
Sutter/Leaders:	n/a	Aluminum	White












Table A - End Support

Minimum distance from edge of hole to inside face of nearest end support SQUARE OR RECTANGULAR HOLE SIZE ROUND HOLE SIZE DEPTH TJIS 2" 3" 4" 5" 6½" 7" 8½" 11" 13" 2" 3" 4" 5" 6½" 7" 8½" 11" 13" 13" 110 11-6" 11-6" 2'-0" 3'-0" 5'-0" 110 11-0" 11-6" 2'-0" 3'-0" 5'-0" 110 11-0" 1

4	210	1'-6"	2'-0"	2'-6"	3'-0"	5'-6"					1'-6"	2'-0"	2'-6"	4'-0"	5'-0"					
92"	230	1'-6"	2'-0"	2'-6"	3'-6"	5'-6"					1'-6"	2'-0"	3'-0"	4'-6"	5'-0"					
	110	1'-0"	1'-0"	1'-6"	2'-0"	2'-6"	3'-0"	5'-6"			1'-0"	1'-6"	2'-0"	2'-6"	4'-6"	5'-0"	6'-0"			
	210	1'-0"	1'-6"	2'-0"	2'-0"	3'-0"	3'-6"	6'-0"			1'-0"	1'-6"	2'-6"	3'-0"	5'-0"	5'-6"	6'-6"			
11}"	230	1'-0"	1'-6"	2'-0"	2'-6"	3'-0"	3'-6"	6'-6"			1'-0"	2'-0"	2'-6"	3'-6"	5'-6"	5'-6"	7'-0"			
[360	1'-6"	2'-0"	3'-0"	3'-6"	4'-6"	5'-0"	7'-0"			1'-6"	2'-6"	3'-6"	4'-6"	6'-6"	6'-6"	7'-6"			
	560	1'-6"	2'-6"	3'-0"	4'-0"	5'-6"	6'-0"	8'-0"			2'-6"	3'-6"	4'-6"	5'-6"	7'-0"	7'-6"	8'-0"			
	110	1'-0"	1'-0"	1'-0"	1'-0"	1'-6"	2'-0"	3'-0"	5'-6"		1'-0"	1'-0"	1'-6"	2'-0"	3'-6"	4'-0"	6'-0"	8'-0"		
	210	1'-0"	1'-0"	1'-0"	1'-6"	2'-0"	2'-6"	3'-6"	6'-0"		1'-0"	1'-0"	2'-0"	2'-6"	4'-0"	4'-6"	6'-6"	8'-6"		
14"	230	1'-0"	1'-0"	1'-0"	1'-6"	2'-6"	2'-6"	4'-0"	7'-0"		1'-0"	1'-0"	2'-0"	3'-0"	4'-0"	5'-0"	7'-0"	9'-0"		
	360	1'-0"	1'-0"	1'-6"	2'-6"	3'-6"	4'-0"	5'-6"	8'-0"		1'-0"	1'-6"	2'-6"	4'-0"	6'-0"	6'-6"	8'-0"	9'-6"		
	560	1'-0"	1'-0"	2'-0"	3'-0"	4'-6"	5'-0"	6'-6"	9'-0"		1'-6"	3'-0"	4'-0"	5'-0"	7'-0"	7'-6"	9'-0"	10'-0"		
	210	1'-0"	1'-0"	1'-0"	1'-0"	1'-0"	1'-6"	2'-6"	3'-6"	6'-0"	1'-0"	1'-0"	1'-0"	2'-0"	3'-0"	3'-6"	6'-6"	8'-0"	11'-0"	
16"	230	1'-0"	1'-0"	1'-0"	1'-0"	1'-6"	1'-6"	3'-0"	4'-0"	7'-0"	1'-0"	1'-0"	1'-0"	2'-0"	3'-6"	4'-0"	7:-0"	9'-0"	11'-0"	
וייי [360	1'-0"	1'-0"	1'-0"	1'-0"	2'-6"	2'-6"	4'-6"	6'-6"	9'-0"	1'-0"	1'-0"	1'-6"	3'-0"	5'-0"	5'-6"	9'-0"	10'-0"	11'-6"	
	560	1'-0"	1'-0"	1'-0"	1'-0"	2'-6"	3'-0"	5'-0"	7'-6"	10'-0"	1'-0"	2'-0"	3'-0"	4'-6"	6'-6"	7'-0"	10'-0"	11'-0"	12'-0"	
							400	400								400			4	Ė
		4"	5"	6"	7*	8"	10"	12"	15"	17"	4"	5"	6"	7"	8"	10"	12"	15"	17"	
18"	360	1'-0"	1'-0"	1'-0"	1'-0"	1'-0"	2'-0"	5'-0"	10'-0"	$ldsymbol{ldsymbol{ldsymbol{eta}}}$	1'-0"	1'-0"	1'-0"	3'-0"	5'-0"	10'-0"	11'-0"	13'-6"		
	560	1'-0"	1'-0"	1'-0"	1'-0"	1'-0"	1'-0"	5'-0"	11'-0"	ldot	1'-0"	1'-0"	1'-6"	4'-0"	6'-6"	11'-0"	12'-0"	14'-6"		
20"	360	1'-0"	1'-0"	1'-0"	1'-0"	1'-0"	1'-0"	2'-0"	7'-0"	10'-6"	1'-0"	1'-0"	1'-0"	1'-0"	2'-6"	8'-0"	11'-6"	14'-0"	15'-6"	
	560	1'-0"	1'-0"	1'-0"	1'-0"	1'-0"	1'-0"	1'-0"	7'-0"	11'-0"	1'-0"	1'-0"	1'-0"	1'-0"	4'-0"	9'-6"	44.4	4 44 44	15'-6"	

Table B - Intermediate or Cantilever Support

JOIST	OLT.	ROUND HOLE SIZE							S	SQUARE OR RECTANGULAR HOLE SIZE											
DEPTH	1310	2"	3"	4"	5"	6 <u>1</u> "	7"	8 7 "	11"	13"		2"	3"	4"	5"	6 <u>1</u> "	7"	8 7 "	11"	13"	Γ
	110	2'-0"	2'-6"	3'-6"	4'-6"	7'-6"					1	1'-6"	2'-6"	3'-6"	5'-6"	6'-6"					Γ
91,	210	2'-0"	2'-6"	3'-6"	5'-0"	8'-0"					2	2'-0"	3'-0"	4'-0"	6'-6"	7'-6"					Γ
95	230	2'-6"	3'-0"	4'-0"	5'-6"	8'-6					2	2'-0"	3'-6"	4'-6"	6'-6"	7'-6"					Γ
	110	1'-0"	1'-0"	1'-6"	2'-6"	4'-0"	4'-6"	8'-6"			1	1'-0"	1'-6"	2'-6"	4'-0"	7'-0"	7'-0"	9'-6"			Γ
	210	1'-0"	1'-0"	2'-0"	3'-0"	4'-6"	5'-0"	9'-0"			1	1'-0"	2'-0"	3'-0"	4'-6"	8'-0"	8'-0"	10'-0"			Γ
112"	230	1'-0"	2'-0"	2'-6"	3'-6"	5'-0"	5'-6"	10'-0"			1	1'-0"	2'-6"	3'-6"	5'-0"	8'-6"	9'-0"	10'-6"			L
	360	2'-0"	3'-0"	4'-0"	5'-6"	7'-0"	7'-6"	11'-0"			2	2'-0"	3'-6"	5'-0"	7'-0"	9'-6"	9'-6"	11'-0"			L
	560	1'-6"	3'-0"	4'-6"	5'-6"	8'-0"	8'-6"	12'-0"			3	3'-0"	4'-6"	6'-0"	8'-0"	10'-6"	11'-0"	12'-0"			L
	110	1'-0"	1'-0"	1'-0"	1'-0"	2'-0"	2'-6"	4'-6"	8'-6"		1	1'-0"	1'-0"	1'-0"	2'-6"	5'-0"	6'-0"	9'-0"	12'-0"		L
L	210	1'-0"	1'-0"	1'-0"	1'-0"	2'-6"	3'-0"	5'-6"	9'-6"		1	1'-0"	1'-0"	2'-0"	3'-6"	6'-0"	7'-0"	10'-0"	13'-0"		L
14"	230	1'-0"	1'-0"	1'-0"	2'-0"	3'-6"	4'-0"	6'-0"	10'-6"		1	<u>1'-0"</u>	1'-0"	2'-6"	4'-0"	6'-6"	7'-6"	11'-0"	13'-6"		L
L	360	1'-0"	1'-0"	2'-0"	3'-6"	5'-6"	6'-0"	8'-6"	12'-6"		1	1'-0"	2'-0"	4'-0"	5'-6"	9'-0"	10'-0"	12'-0"	14'-0"		L
	560	1'-0"	1'-0"	1'-6"	3'-6"	5'-6"	6'-6"	9'-6"	13'-6"		1	1'-0"	3'-0"	5'-0"	7'-0"	10'-0"	11'-0"	13'-6"	15'-0"		L
L	210	1'-0"	1'-0"	1'-0"	1'-0"	1'-0"	1'-0"	3'-6"	6'-0"	10'-0"	1	1'-0"	1'-0"	1'-0"	1'-6"	4'-6"	5'-6"	10'-0"	12'-6"	16'-0"	L
16"	230	1'-0"	1'-0"	1'-0"	1'-0"	1'-6"	2'-0"	4'-0"	6'-6"	11'-0"	1	1'-0"	1'-0"	1'-0"	2'-6"	5'-0"		10'-6"			
L	360	1'-0"	1'-0"	1'-0"	1'-0"	3'-0"	4'-0"		10'-0"		1	1'-0"	1'-0"	2'-0"	4'-0"	7'-6"		13'-0"			
	560	1'-0"	1'-0"	1'-0"	1'-0"	2'-6"	3'-6"	7'-0"	11'-0"	15'-0"	1	1'-0"	1'-0"	3'-6"	5'-6"	9'-0"	10'-0"	14'-6"	16'-0"	18'-0"	L
		4"	5"	6"	7"	8"	10"	12"	15"	17"		4"	5"	6"	7"	8"	10"	12"	15"	17"	Г
400	360	1'-0"	1'-0"	1'-0"	1'-6"	3'-0"	6'-0"		15'-0"			1'-0"	1'-6"	4'-0"	6'-6"	9'-0"	14'-6"		19'-6"		t
18" -	560	1'-0"	1'-0"		1'-0"	2'-0"			16'-6"			1'-0"	3'-6"	6'-0"	_			18'-0"	_		t
	360	1'-0"	1'-0"		1'-0"	1'-0"	3'-0"		11'-0"	15'-6"	_	1'-0"	1'-0"	1'-6"	4'-0"			16'-6"			t
20" -	560	1'-0"	1'-0"	1'-0"	1'-0"	1'-0"	1'-6"		12'-0"			1'-0"	1'-0"	3'-0"	6'-0"					20'-6"	-

Rectangular holes based on measurement of longest side.


• Holes may be located vertically anywhere within the web. Leave 1 of web (minimum) at top and bottom of hole.

• Knockouts are located in web at approximately 12" on-center; they do not affect hole placement. • For simple span (5' minimum), uniformly loaded joists used in residential applications, one maximum size round hole may be located

at the center of the joist span provided that no other holes occur in the joist. Distances are based on the maximum uniform loads from current iLevel specifier's guides. For other load conditions or hole configurations use iLevel® TJ-Beam® software or contact your iLevel representative.

See Weyerhaeuser For Other Specifications

ALLOWABLE HOLES - Headers and Beams 1.55E TimberStrand® LSL Headers and Beams



Allowed hole zone suitable for headers and beams with

- uniform and/or concentrated loads.
- Round holes only No holes in headers or beams in plank orientation

Other iLevel® Trus Joist® Headers and Beams \pt147;Microllam® LVL and Parallam® _ \pt45.5,147;2 x diameter of the largest hole (minimum) hole zone \pt147;Microllam® LVL and Parallam® PSL allowed hole

DO NOT cut, notch or drill holes in headers or beams except as indicated in illustrations and tables.

- Allowed hole zone suitable for headers and beams with uniform loads only.
- Round holes only
- No holes in cantilevers. No holes in headers or beams in plank orientation.

See Weyerhaeuser For Other Specifications

ALLONABLE HOLES - Headers & Beams

NO SCALE

5

chitect




 \bigcirc

Town Comments | 11/11/20 RPRC Date Revision

April 29, 2020 Job No

220-024 Drawing





Plant List

45 Byram Ridge Road, Armonk, NY

Abb.	Botanical Name	Common Name	Size	Quan
	duous Trees			
AC	Amalanchier carnea	Red Horsechestnut	14-16' ht.	2
LT	Liriodendron tulipifera	Tulip Tree	14-16' ht.	5
Mino	or Trees			
CF	Cornus florida	Flowering Dogwood	7-8' ht.	2
СК	Cornus kousa	Kousa Dogwood	7-8' ht.	1
PK	Prunus kwanzan	Kwanzan Cherry	8-10' ht.	2
Shru	<u>bs</u>			
AP	Aesculus parviflora	Bottlebrush Buckeye	4-5' ht.	3
BG	Buxus microphylla	Green Mountain Boxwood	2.5-3' ht.	16
cs	Cheanomeles speciosa	Flowering Quince	4-5' ht.	2
LF	Leucothoe fontesiana	Drooping Leucothoe	2.5-3' sp.	2
LO	Ligustrum ovalifolium	California Privet	5-6' ht.	50
PF	Potentilla fruticosa	Abbotswood Potentilla	3-3.5' ht.	12
PJ	Pieris jap. Mtn. Fire	Mountain Fire Andromeda	3-3.5' ht.	2
PL	Prunus laurocerasus	Otto Luyken Laurel	3.5-4' ht.	14
SB	Spirea bumalda	A. Waterer Spirea	2.5-3' ht.	6
VD	Viburnum dentatum	Arrowwood	4-4.5' ht.	3
VR	Viburnun rhytidophyllum	Leatherleaf Viburnum	4.5-5' ht.	9
Note	<u>es:</u>			


- 1. All plants to be healthy, full and of a form typical of the species at planting, and warranted in the same condition for 2 full growing seasons.
- 2. All trees to have 18" of topsoil around the roots, shrubs 12.
- 3. All plants and plant beds to be mulched with 2" of brown shredded cedar.
- 4. Edge beds with edging tool.
- 5. Water all plants thoroughly at planting, and weekly during the first 2 growing seasons as necessary.

Notesi

I. This drawing is for plant material specification only. All base data by others. No representation or warranty is express or implied as to accuracy of same.

2. Contractor is responsible for safety of site during installation of all improvements. Thereafter the owner is responsible for maintaining a safe site.

3. All environmental constraints subject to local, state and/or federal jurisdiction must be reviewed and approved by appropriate agencies.



Stephen Lopez, AICP, RLA 254 Bedford Road, Pleasantville, NY 10570

Landscape Plan 45 Byram Ridge Road Armonk, NY

Date: March 1, 2021 Scale: As Shown